DMV Lane Technician Observation Report

DMV Technician: Griffith Round Position: 1 or 2						
Station: NO Date: 9-17-12 Time: 2:07						
Vehicle Make: Merrelins Buy Model @ 320 Year 2003					3	
GVWR:	GVWR: Fuel Type: 645 Registration Number: 30022					
Auditor: Com	Auditor: Court / Overt (circle one)					
				YES	NO	N/A
		er work and verify VI	N number?	6		
2. Was Emissions testing required?			1			
a) Was Emissions testing performed using OBD?						
b) Was Emissions testing performed using Analyzer Probe?						-
c) Was Emissions testing performed using Paddle(s)?						6
d) Was Emissions testing performed using Clip?						1
3. Was Catalytic Converter inspection required?					6	
a) Was Catalytic	c Converter inspe	ction performed?				-
4. Was Fuel Tank pressure testing required?				1		
a) Was Fuel Tank pressure testing performed?					6	
5. Was Fuel Cap pressure testing required?				1		
a) Was Fuel Cap pressure testing performed?					-	
6. Is this test a Re-check from a prior failure?				1		
a) Which re-check test is being performed? 1 2 3 (circle one)						
b) If this is re-check #3, was repair paperwork verified for waiver?						
New Castle and I	Kent Counties O	nly				
7. Was Two-Speed Idle testing required?					~	
a) Was Two-Speed Idle testing performed?						
Sussex County O	nly					
8. Was Curb Idle testing required?						
a) Was Curb Idl	le testing performe	ed?				
Comment:						3
The state of the s						

DMV Lane Technician Observation Report

DMV Technician: Overas Miguel Position: 1 or 2							
Station: Date: 9-17-12 Time: 1:05							
Vehicle Make: 4 Model 40 oon		Year 2002					
GVWR: Fuel Type: GAS Registration N	umber: 942 834						
Auditor: Covert And Covert (circle one)							
	YES	NO	N/A				
1. Did technician check vehicle paper work and verify VIN number?	6						
2. Was Emissions testing required?	1						
a) Was Emissions testing performed using OBD?	1						
b) Was Emissions testing performed using Analyzer Probe?			_				
c) Was Emissions testing performed using Paddle(s)?			6				
d) Was Emissions testing performed using Clip?			-				
3. Was Catalytic Converter inspection required?		-					
a) Was Catalytic Converter inspection performed?		1	6				
4. Was Fuel Tank pressure testing required?		6					
a) Was Fuel Tank pressure testing performed?			-				
5. Was Fuel Cap pressure testing required?		4					
a) Was Fuel Cap pressure testing performed?			4				
6. Is this test a Re-check from a prior failure?		1					
a) Which re-check test is being performed? 1 2 3 (circle one)							
b) If this is re-check #3, was repair paperwork verified for waiver?							
New Castle and Kent Counties Only							
7. Was Two-Speed Idle testing required?							
a) Was Two-Speed Idle testing performed?							
Sussex County Only							
8. Was Curb Idle testing required?							
a) Was Curb Idle testing performed?			-				
Comment:							